



**SAFETY SYSTEM®**  
YOUR PROTECTOR

**Sir Safety System S.p.A. Single-member company**  
Wholly-owned subsidiary of Sir Holding Srl  
Via dei Fornaciai, 9 - Santa Maria degli Angeli  
06081 Assisi - Perugia - Italy  
Tel.+39 075.8043737 - Fax +39 075.8048686

VAT Nr. IT 03359340548  
Viale Europa 74  
20090 Cusago Milano  
Tel. +39 02.90394575  
Fax +39 02.90394441

**TECHNICAL SHEET**

**export@sirsafety.com**  
**www.sirsafety.com**

Quality Management  
System Certificate  
UNI EN ISO 9001:2015

|                            |                       |                                  |
|----------------------------|-----------------------|----------------------------------|
| <b>Name: COSMOS HELMET</b> | <b>Code: MD1211K1</b> | <b>MD12 POLYETHYLENE HELMETS</b> |
|----------------------------|-----------------------|----------------------------------|

**Description**

Helmet in polyethylene with polyethylene four-point head harness. With slots for fitting earmuffs, chinstrap attachment, ratchet wheel for size adjustment and sweatband.  
Weight 330 g.

The product has been designed and manufactured to comply with Regulation (EU) 2016/425 and subsequent amendments.



|                       |                         |                                 |
|-----------------------|-------------------------|---------------------------------|
| Category<br><b>II</b> | Colours<br><b>WHITE</b> | Available Sizes<br><b>UNICA</b> |
|-----------------------|-------------------------|---------------------------------|

|  |                               |   |
|--|-------------------------------|---|
| Quantity/Carton<br><br><br><br><br><br><br><br><br><br><b>36</b> | EC Standards<br><b>EN 397</b> | Important Information<br>This helmet has been designed to protect the head against the risk of falling objects and mechanical shocks' hazard.<br><br>Make sure the helmet is in good condition before use and its surface is not damaged: inspect for cracking, abrasions, change of colouring or dents. Once you become aware of a damage, you should immediately replace it.<br><br>Keep in cool, dry place, away from heat sources and direct sunlight.<br>Clean all its parts on a regular basis with a moist cloth and soapy water or non-aggressive detergent. Do not use any solvents. |
| Dexterity  |                               |   |